BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 786 Date : 8/10/2020

1. Customer's Name and Address : AEE. BBMP.
   With Telephone No. Byatarayanapura Sub division.
2. Well Location : Vinayakanagara 3rd Main
3. Total Well Depth / Drilled in Ft. : 1305 feet.
4. Casing Erected in Ft. : 190 feet.
5. Water Struck at the Depth of : 620 feet.
6. Total Yield (Measuring method "V" North 2 inch. / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clay.
8. At the Depth of : 1225 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE Bwssb NOS

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 787 Date : 11.10.2020

1. Customer's Name and Address : AEE. BBMP. Byatarayanapura Sub division.
   With Telephone No.
2. Well Location : Shivapura 6th cross.
3. Total Well Depth / Drilled in Ft. : 1312 feet.
4. Casing Erected in Ft. : 197 feet.
5. Water Struck at the Depth of : 590 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear clear.
8. At the Depth of : 1212 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Rs100.00
Mode of pay Cash
Purpose Non Revenue
Non Revenue categoryREG-FEE
One Hundred Rupees Only

Scanned by CamScanner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

BOREWELL COMPLETION REPORT

No. 788

Date : 14.10.2020

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura Sub Division.
2. Well Location : Sapthagiri I St Main
3. Total Well Depth / Drilled in Ft. : 1302 Feet.
4. Casing Erected in Ft. : 197 Feet.
5. Water Struck at the Depth of : 550 Feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : clay
8. At the Depth of : 1210 Feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Rs100.00
Mode of pay Cash
Purpose Non Revenue
Non Revenue category REG-FEE
One Hundred Rupees Only

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 789 Date : 16/10/2020

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura Sub Division.
2. Well Location : Sapthagiri Layout Near Govindarajaha...
3. Total Well Depth / Drilled in Ft. : 1309 feet.
4. Casing Erected in Ft. : 192 feet.
5. Water Struck at the Depth of : 530 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1230 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE Ward No 6

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Rs100.00
Mode of pay Cash
Purpose Non Revenue
Non Revenue category REG-FEE
One Hundred Rupees Only

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 790 Date : 19/10/2020

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura
   Sub division.
2. Well Location : Ambedkar nagara Near Samudaya Bhavana
3. Total Well Depth / Drilled in Ft. : 1306 Feet.
4. Casing Erected in Ft. : 204 Feet.
5. Water Struck at the Depth of : 505 Feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1230 Feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Rs100.00
Mode of pay Cash
Purpose Non Revenue
Non Revenue category RED-FEE

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 791

Date : 22/10/2020

1. Customer's Name and Address With Telephone No. : AEE BBMP. Byatarayanapura sub division.
2. Well Location : Jakkur near govt school
3. Total Well Depth / Drilled in Ft. : 1300 feet.
4. Casing Erected in Ft. : 191 feet.
5. Water Struck at the Depth of : 570 feet.
6. Total Yield (Measuring method "V" North 2 inch. / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : clear.
8. At the Depth of : 1200 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE ward No 8 ಸಹಿ ಮತ್ತು ಸೀಲ್

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Mode of pay Cash
Purpose Non Revenue
Non Revenue category REG-FEE

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 792

Date 25/10/2020

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura Sub division.
2. Well Location : Palanahalli Lane (Defence colony)
3. Total Well Depth / Drilled in Ft. : 1306 Feet.
4. Casing Erected in Ft. : 197 Feet.
5. Water Struck at the Depth of : 510 Feet
6. Total Yield (Measuring method "V" North 1½ inch / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1225 Feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Rs100.00
Mode of pay Cash
Purpose Non Revenue
Non Revenue categoryREG-FEE

One Hundred Rupees Only

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 793 Date : 27/10/2020

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura Sub division.
2. Well Location : Babanagara I st stage 2nd cross
3. Total Well Depth / Drilled in Ft. : 1309 feet.
4. Casing Erected in Ft. : 197 feet.
5. Water Struck at the Depth of : 555 feet.
6. Total Yield (Measuring method "V" North 1½ inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : clay.
8. At the Depth of : 1215 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Rs100.00
Mode of pay Cash
Purpose Non Revenue
Non Revenue category REG-FEE
One Hundred Rupees Only

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 794

Date : 30/10/2020

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura SWS division.
2. Well Location : Balaji layout (Kogilu) 1st main
3. Total Well Depth / Drilled in Ft. : 1312 feet.
4. Casing Erected in Ft. : 182 feet.
5. Water Struck at the Depth of : 560 feet.
6. Total Yield (Measuring method "V" North 2 inch. / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : clear.
8. At the Depth of : 1232 feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

N. Ravi

Party's Signature

Manager / ~~Proprietor~~

Mode of pay Cash
Purpose Non Revenue
Non Revenue category REG-FEE

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 795

Date : 2.1.1.2020

1. Customer's Name and Address With Telephone No. : AEE BBMP Byatarayanapura Sub Division
2. Well Location : Ayyappa layout 2nd cross (Cooling)
3. Total Well Depth / Drilled in Ft. : 1306 feet
4. Casing Erected in Ft. : 211 feet.
5. Water Struck at the Depth of : 570 feet.
6. Total Yield (Measuring method "V" North 2½ inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : clear.
8. At the Depth of : 1216 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE well No 5 ಅಯ್ಯಪ್ಪ ಲೇಔಟ್ 5ನೇ ಕ್ರಾಸ್

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Mode of pay Cash
Purpose Non Revenue
Non Revenue categoryREG-FEE

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 796 Date : 4/11/2020

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura Sub division.
2. Well Location : Kempegowda layout.
3. Total Well Depth / Drilled in Ft. : 1303 feet.
4. Casing Erected in Ft. : 214 feet.
5. Water Struck at the Depth of : 565 feet.
6. Total Yield (Measuring method "V" North 1½ inch / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : clear
8. At the Depth of : 1216 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

RR Number

Rs100.00

Mode of pay Cash

Purpose Non Revenue

Non Revenue categoryREG-FEE

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 797

Date : 6/11/2020

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub division.
2. Well Location : Muneshwara layout 3rd cross
3. Total Well Depth / Drilled in Ft. : 1309 Feet.
4. Casing Erected in Ft. : 192 Feet.
5. Water Struck at the Depth of : 602 Feet.
6. Total Yield (Measuring method "V" North 2 inch. / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1227 Feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

As work as per Department Engineer

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / ~~Proprietor~~

Party's Signature

RR Number 8

Rs100.00

Mode of pay Cash

Purpose Non Revenue

Non Revenue category REG-FEE

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 798

Date : 9/11/2020

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura Sub division.
2. Well Location : Prakruthi Layout.
3. Total Well Depth / Drilled in Ft. : 1303 feet.
4. Casing Erected in Ft. : 197 feet.
5. Water Struck at the Depth of : 565 feet.
6. Total Yield (Measuring method "V" North 1 1/2 inches / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1210 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / ~~Proprietor~~

Party's Signature

Purpose Non Revenue

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 799

Date : 11/11/2020

1. Customer's Name and Address With Telephone No. : AEE BBMP Byatarayanapura Sub division
2. Well Location : Vinayakanagara, 5th cross
3. Total Well Depth / Drilled in Ft. : 1312 feet
4. Casing Erected in Ft. : 187 feet
5. Water Struck at the Depth of : Failur
6. Total Yield (Measuring method "V" North — / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear —
8. At the Depth of : —
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

AE ward No 5

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Manager / ~~Proprietor~~

Party's Signature

Mode of pay Cash
Purpose Non Revenue

Scanned by CamScanner